


Date: Thursday, 15/01/2009 3:15:46 PM
 User: Linda Lacelle

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: CROSSTUBE SUPPORT CHANGE
Job Number	: 44856		
Estimate Number	: 13358		
P.O. Number	:	Part Number	: DSI9415011
This Issue	: 15/01/2009	S.O. No.	:
Prsht Rev.	: NC	Drawing Number	: DSI9415
First Issue	: / /	Project Number	: N/A
Previous Run	:	Drawing Revision	: A
Written By	: 	Material	:
Checked & Approved By	:	Due Date	: 22/01/2009
Comment	: Est Rev:A 08-06-03 new issue DD verified by:EC	Qty:	1
		Um:	Each

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	DC	DOCUMENT CONTROL
-----	----	------------------



for JTD 09/01/15



Comment: Photocopy bluefile & type labels per PPP DSI9415-011 CHG001

2.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1
 Pick Packing Kit

3.0	D3595075395	RUBBER CUSHION .75" x 3.95
-----	-------------	----------------------------



Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)
 RUBBER CUSHION .75" x 3.95
 batch: *42998*

9/1/15

(1x)

SL

4.0	QC4	INSPECT 100% KITS FOR COMPLETENESS
-----	-----	------------------------------------



Comment: INSPECT 100% KITS FOR COMPLETENESS

509/01/15 GC

5.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1
 Identify and pack for shipping as per PPP DSI9415-011
 Location:
 PPP Rev: *Draft*

9/1/15

(1x)

SL

Date: Thursday, 15/01/2009 3:15:46 PM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: CROSSTUBE SUPPORT CHANGE

Job Number: 44856

Part Number: DSI9415011

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC21

FINAL INSPECTION/W/O RELEASE



09/01/15 JA

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



MF 09-01-15